

# Oil Field Environmental Incident Summary

**Incident:** 20150731143906      **Date/Time of Notice:** 07/31/2015 14:39

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** EN-HANSON-156-94- 3031H-1

**Field Name:** MANITOU

**Well File #:** 18187

**Date Incident:** 7/30/2015

**Time Incident:** 16:45

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 156

**Rng:** 94

**Sec:** 30

**Qtr:**

**Location Description:**

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Jason Henry  
3015 16th Street SW, Suite 20  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1600 Feet

**Distance Nearest Water Well:** 1600 Feet

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

|       | Spilled | Units   | Recovered | Units   | Followup | Units   |
|-------|---------|---------|-----------|---------|----------|---------|
| Oil   |         |         |           |         |          |         |
| Brine |         |         |           |         |          |         |
| Other | 120     | Barrels | 100       | Barrels | 100      | barrels |

**Description of Other Released Contaminant:**

Emulsion

**Inspected:**

**Written Report Received:** 9/24/2015

**Clean Up Concluded:** 8/17/2015

**Risk Evaluation:**

There is no immediate risk to report at this time.

**Areal Extent:**

Some of the release left location, running approximately 80' offsite into a pasture.

**Potential Environmental Impacts:**

There are some potential environmental impacts to the Well/Facility soil as well as potential impacts to the topsoil/pasture area offsite.

**Action Taken or Planned:**

An initial verbal notification was made by Jason Henry to the NDIC today (07-31-2015) at 11:00 am.

A vacuum truck was dispatched (7/30/2015) and recovered 100 bbl. of emulsion. An additional vacuum truck was dispatched to return to location (7/31/2015) to recover the remaining standing emulsion (approximately 10-20 bbl.) Strata was dispatched (7/30/2015) and placed an emergency ND one-call to begin cleanup. Strata constructed a temporary berm in the pasture to the south to prevent the release from spreading and also plugged the culvert between the H-1 and H-2&3 pads to prevent further run-off. Strata arrived on location (7/31/2015) to continue cleanup, beginning with hydro work around the emulsion header to enable maintenance to make repairs as soon as possible.

**Wastes Disposal Location:** The waste will be taken to an approved waste disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 7/31/2015    **Status:** Reviewed - Follow-up Required

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release has impacted soils outside of an E&P well pad. Followup is required.

---

**Date:** 8/4/2015    **Status:** Inspection

**Author:** Kangas, Kathleen

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site at 4 p.m. (08.04.15). 90 degrees, sunny, wind 13 mph SSE. 120 bbls of emulsion. Some impact off site. Cleanup crew is on site now. Spoke to staff on site. Side dumps leaving with contaminated soil. Large hole where contaminated soil has been removed.